

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403152570

Date Received:
08/31/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10734
Name of Operator: HIGH RIVER RESOURCES OPERATING LLC
Address: 3838 OAK LAWN AVE SUITE 710
City: DALLAS State: TX Zip: 75219
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Archuleta, Amy		aarchuleta@highriverllc.com
Labowskie, Steve		steve.labowskie@state.co.us
Mickey Ahrens		mahrens@highriverllc.com
Vaughn, Robert		rvaughn@highriverllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500353
Inspection Date: 08/29/2022 FIR Submit Date: 08/30/2022 FIR Status:

Inspected Operator Information:

Company Name: HIGH RIVER RESOURCES OPERATING LLC Company Number: 10734
Address: 3838 OAK LAWN AVE SUITE 710
City: DALLAS State: TX Zip: 75219

LOCATION - Location ID: 333517

Location Name: BONDAD 34-10-M34N10W Number: 36NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M
Latitude: 37.144740 Longitude: -107.881780

FACILITY - API Number: 05-067-00 Facility ID: 214279

Facility Name: BONDAD 34-10 Number: 1-36
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M
Latitude: 37.144740 Longitude: -107.881780

CORRECTIVE ACTIONS:

1 CA# 164209

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 09/29/2022

Response: CA COMPLETED

Date of Completion: 08/31/2022

The metal secondary containment has been repaired.

The ball valve handle was also removed.

Signed:

Date: 8/31/2022 10:54:31 AM

Total Attach: 1 Files