

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2022

Submitted Date:

08/31/2022

Document Number:

693507819**FIELD INSPECTION FORM**Loc ID 474767 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 1125 17TH STREET SUITE 550City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Cugnetti, Mike		Mcugnetti@verdadoil.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477665	WELL	PR	06/01/2022	OW	123-51164	County Line 3130-04H	PR

General Comment:

Inspected Facilities

Facility ID: 477665 Type: WELL API Number: 123-51164 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
Field Inspector Assigned: Randy Silver
Complaint Received
Date: 8-26-2022
Complaint Contacted: Yes via phone
Date: 8-26-2022 Time: 8:30AM
Location ID #474767
Location name: County line pad
Inspection Document # 693507815
Complaint inspection document # 693507819
Complaint Document form 18 # 403147813
Nature of Complaint: Noise
Field Inspector Actions:
On 8-26-2022, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Shane Hall 120 Weld County Road 39 Brighton CO stated the issues were occurring outside of complainants home.
On 8-26-2022, I attempted to make contact with the complainant who indicated experiencing an ongoing problem with vibration and loud hissing from the county line pad (Missouri 31).
I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I spoke with site operator he stated they had an issue with the site being shut down due to O2. He stated that they were purging the line to bring site back on line through the ECD. ECD did make said noise during upset condition.
Operator informed me at time of inspection they were fixing issue so it would not happen in the future. This is considered an upset condition not a normal part of operations.
Weather conditions: Clear
No violation of COGCC rules were observed at the time of the inspection.
All information has been reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action:

Date: