

Inspection Photos and Issue Report

9/7/2022

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #324421

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



September 7, 2022

Photo 1: Photo taken from the southwest, and provides an overview of the Location. Photo shows Location has not been recontoured/regraded and reclaimed in accordance with 1004 rules; fill slope remains evident and bare; berms along southeastern perimeter remains apparent.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #324421



Photo 2: Photo shows bare fill slope; location has not been recontoured/regraded and reclaimed.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #324421



September 7, 2022



September 7, 2022

Photo 3: Photos taken from the southeast end of the Location, facing northwest. Photo shows location has not been recontoured/regraded and reclaimed in accordance with 1004 rules.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #324421



Photo 4: Photos examples showing berm remaining along the southeastern perimeter of the Location; possibly topsoil. Location has not been recontoured/regraded and reclaimed in accordance with 1004 rules.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #324421



Photo 5: Photo taken from the central area of the Location; photo shows topsoil does not appear to have been replaced; soils observed appear to be subsoils.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #324421



Photo 6: Continued from photo 5. Photo shows additional areas of the Location where topsoils do not appear to have been replaced.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #324421



September 7, 2022



September 7, 2022

Photo 7: Photos show vegetation and soils of the reference area.