

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2022

Submitted Date:

09/15/2022

Document Number:

701103570

FIELD INSPECTION FORM
 Loc ID 424711 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10396

Name of Operator: SWN PRODUCTION COMPANY LLC

Address: P.O. BOX 12359

City: SPRING State: TX Zip: 77391-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
O'Malley, Anna		anna.omalley@state.co.us	
Pate, James		jsconcrete@yahoo.com	All Inspections
Stepp, Sarah		wccassistant@gmail.com	All Inspections
, SWN		swnsandwash@swn.com	All Inspections
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424708	WELL	SI	02/01/2022	OW	107-06242	Dawson Creek 1-25	SI

General Comment:

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No sign at tank battery meeting Rule 605.e..
 - 500 gallon (11.9 bbl) methanol tank at wellhead. Methanol tank and propane tank missing information required for tanks over 10 bbls.
 - Propane tank not identified as a hazard and appropriate warning signs posted.
- A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Uncorrective Actions from 7/19/2022 inspection # 702800461

- It was observed in this inspection that CO List B Noxious Weeds are present throughout the Location, including on the working pad area, in stormwater ditches and Location perimeter berms. Species include Canada and bull thistle, houndstongue and whitetop.
- It was observed in this inspection that the Location, including the access road and around production equipment is overgrown with vegetation.
- Unused equipment including 2 tank stands, and 1 secondary containment tank were observed stored at the well area.
- It was observed in this inspection that wildlife protection devices to prevent wildlife, including but not limited to birds and bats from entering the secondary containment. stock tank adjacent to the wellhead are missing or insufficient.
- Impacted soils observed around the wellhead and at the production equipment at the north of the Location. The containment device at the spill at the north of the Location was observed to be insufficient.

Refer to 7/19/2022 inspection # 702800461 for corrective action in Reclamation section.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Road into location is over grown with vegetation.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Propane tank not identified as a hazard and appropriate warning signs posted.		
Corrective Action:	Install sign to comply with Rule 605.h. Rule 610.c.(4)	Date:	11/15/2022
Type	TANK LABELS/PLACARDS		
Comment:	500 gallon (11.9 bbl) methanol tank at wellhead. Methanol tank and propane tank missing information required for tanks over 10 bbls.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/15/2022
Type	BATTERY		
Comment:	No sign at tank battery meeting Rule 605.e..		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/15/2022
Type	WELLHEAD		
Comment:	Signs have Beeman Oil & Gas on signs. Form 9 Transfer of Operatoship doc# 403026381 is in Process		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	It was observed in this inspection that CO List B Noxious Weeds are present throughout the Location, including on the working pad area, in stormwater ditches and Location perimeter berms. Species include Canada and bull thistle, houndstongue and whitetop. Uncorrective Action from 7/19/2022 inspection # 702800461		
Corrective Action:	Conduct weed management to prevent further establishment and spread of Noxious Weeds; ongoing weed management required until location passes final reclamation.	Date:	07/25/2022
Type	WEEDS		
Comment:	It was observed in this inspection that the Location, including the access road and around production equipment is overgrown with vegetation. Uncorrective Action from 7/19/2022 inspection # 702800461		
Corrective Action:	Comply with Rule 606.	Date:	07/27/2022
Type	STORAGE OF SUPL		
Comment:	Unused equipment including 2 tank stands, and 1 secondary containment tank were observed stored at the well area. Uncorrective Action from 7/19/2022 inspection # 702800461		
Corrective Action:	Comply with Rule 606.	Date:	08/04/2022
Overall Good: <input type="checkbox"/>			

Spills:				
Type	Area	Volume		
Other				
Comment:	Impacted soils observed around the wellhead and at the production equipment at the north of the Location. The containment device at the spill at the north of the Location was observed to be insufficient.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition. Remove and properly dispose of impacted material as E&P waste. Properly dispose of oily waste in accordance with 905.e.			Date: <u>08/04/2022</u>

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Other	#		
Comment:	It was observed in this inspection that wildlife protection devices to prevent wildlife, including but not limited to birds and bats from entering the secondary containment stock tank adjacent to the wellhead are missing or insufficient. Uncorrective Action from 7/19/2022 inspection # 702800461		
Corrective Action:	Install or repair wildlife protection equipment.		Date: <u>07/25/2022</u>

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 424708 Type: WELL API Number: 107-06242 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in since Febuary 2022

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103576	Inspection 701103570 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861536