

# Inspection Photos and Issue Report

9/20/2022

Operator: VISION ENERGY LLC - 10770

Location #312658

Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022



September 20, 2022

**Photo 1:** Photos taken from the north end of the Location, facing southeast and southwest. Photos provide overview of the Location.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



**Photo 2:** Photo example showing noxious weeds remain established on the Location.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022

**Photo 3:** Photo example showing BMPs to stabilize the Location, and to minimize tracking and sediment transport remain missing or insufficient.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022



September 20, 2022

**Photo 4:** Photos examples showing vegetation remains established around production equipment. Photo right also shows sign at well remains inadequate.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022



September 20, 2022

**Photo 5:** Photos examples showing areas vegetation remains established at the secondary containment BMP; secondary containment is not in proper functioning condition, or adequate in size to contain a spill from the tank. Vegetation within BMP compromises the impermeability of the containment.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



**Photo 6:** Labeling on tank does not comport with Rule 605.h

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022



September 20, 2022

**Photo 7:** Photos taken from the west end of the Location. Photo shows stormwater runoff from the location has not been managed in a manner that minimizes erosion and degradation; gully erosion evident on offsite areas west of Location (photo right).

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022



September 20, 2022

**Photo 8:** Photos 8-10 taken from the east end of the Location. Photos show stormwater and erosion control BMPs to stabilize the location and manage runoff remain missing or insufficient; erosion degradation has persisted.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



September 20, 2022



September 20, 2022

**Photo 9:** See comments under photo 8.

Inspection Photos  
Operator Name: VISION ENERGY LLC - 10770  
Location #312658



**Photo 6:** See comments under photo 8.