

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2022

Submitted Date:

09/16/2022

Document Number:

694500514

FIELD INSPECTION FORMLoc ID 467526 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Joda, Ken	303-916-3854	ken@d90energy.com	

General Comment:

on 9/15/2022 COGCC staff, Kris Neidel inspected the Spicer Annex Pad. Weather was 65 degrees and had been raining on and off all day. Crews were installing subsurface flowlines at the wellheads. Equipment from the recent drill were on location. One cuttings bin was on location and had some cuttings on the pad around the bin. It appeared that some of the cuttings had been driven into the pad. (from where the rig shakers were to where the cuttings bin is). A skid from the rig was on the south side of the pad had, what appeared to be some granular chemicals spilled on them. Corrective Actions: remove and properly dispose of chemical spill. Clean and dispose (As E&P waste) cuttings from around cuttings bin and scrape from the pad, verify with soil samples.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	A skid from the rig was on the south side of the pad had what appeared to be some granular chemicals spilled on them.		
Corrective Action:	remove and properly dispose of chemical spill.		Date: 09/23/2022
Type	OTHER		
Comment:	some cuttings from where the rig shakers were to where the cuttings bin is , were tracked and driven into the pad.		
Corrective Action:	. Clean and dispose (As E&P waste) cuttings from around cuttings bin and scrape from the pad, verify with soil samples.		Date: 09/23/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403169661	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862934
694500515	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862929