

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403165631

Date Received:  
09/14/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 8 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203994

Inspection Date: 08/17/2022

FIR Submit Date: 08/22/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 467272

Location Name: ELU J14 Number: FED-496 PAD County: \_\_\_\_\_

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

FACILITY - API Number: 05-103-00 Facility ID: 467272

Facility Name: ELU J14 Number: FED-496 PAD

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

CORRECTIVE ACTIONS:

6  CA# 164027

Corrective Action: Comply with Rule 1002.b and 1002.c

Date: 06/18/2022

Response: CA COMPLETED

Date of Completion: 09/09/2022

Operator Comment: Installed berm along the inside of the topsoil stockpiles and reinstalled wattles along the outside of the topsoil stockpiles segregating the topsoil from any subsoils. Also reformed the topsoil stockpiles preparing the topsoil for hydro seed and mulch.

COGCC Decision: Not Approved

COGCC Representative: Per site visit 9/27/2022 between Caerus and COGCC Staff, it was observed that work to address corrective action(s) were "in-process", but not yet resolved.

8 CA# 164029

Corrective Action: Install or repair required BMPs per Rule 1002.f. Ensure control measures are adequate for the site's conditions, implemented in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 05/25/2022

Response: CA COMPLETED Date of Completion: 09/09/2022

Operator Comment: Repaired and reinstalled berm and wattles associated with topsoil stockpiles. Also repaired sediment basins and installed inlet and outlet rock armor.

COGCC Decision: Not Approved

COGCC Representative: Per site visit 9/27/2022 between Caerus and COGCC Staff, it was observed that work to address corrective action(s) were "in-process", but not yet resolved.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden Signed:

Title: EHS Date: 9/14/2022 9:49:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403165631	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files