

IT APPEARS ON FLIR VIDEO THAT BOTH TANKS ARE VENTING THROUGH OPEN ENDED 2" RISERS ON CRUDE OIL TANKS. THERE IS NO EQUIPMENT TO CONTROL GAS ON 2" RISERS ON TANKS.

CA: Immediately cease venting/flaring.

-Upon phone notification by COGCC Field Inspector Tom Beardslee, Operator immediately dispatched crew to bull-plug overflow tank and install Enardo Valve (6 oz) on production tank. Spring loaded thief hatches (4-oz) were already installed on each tank. Operator is scheduling additional FLIR imaging the week of 10/03/22, to confirm control of emissions

