

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/29/2022

Submitted Date:

10/05/2022

Document Number:

690103213

FIELD INSPECTION FORMLoc ID 408511 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 24461

Name of Operator: DIVERSIFIED OPERATING CORPORATION

Address: 10455 W 73RD PLACE

City: ARVADA State: CO Zip: 80005

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
		wlw4@comcast.net	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
WARBURTON, BILL		wlw@doccolo.com	
		tjcammon@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246602	WELL	PA	08/15/2001	OW	123-14399	ROTH 12-7	PA
408511	LOCATION	CL			-	ROTH-67N59W 7NWSW	EG

General Comment:

Engineering Integrity inspection performed on September 29th, 2022 in response to COGCC form 18 complaint Doc #403174143 received on 09/22/2022 that outlines: Diversified last known operator and abandoned. Flowline left sticking 4 ft out of ground and impeding farming operations. Would like removed or dug down and cut off.

Corrective Actions Required identified during this field inspection are outlined in the flowline and housekeeping sections of report. Photos uploaded.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment: Misc pipe, wood and rock debris observed on/ around Roth 12-7 location

Corrective Action: Remove trash and debris per COGCC rule 606.d

Date: 11/11/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 246602 Type: WELL API Number: 123-14399 Status: PA Insp. Status: PA

Facility ID: 408511 Type: LOCATION API Number: - Status: CL Insp. Status: EG

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: (1) 2" flowline riser (open ended/ OOS) observed in close proximity to Roth 12-7 PA well. Flowline abandonment has not been completed per COGCC rule 1105.e

Corrective Action: Complete flowline abandonment per COGCC rule 1105.e (see comment section of report); or remove flowline

Date: 11/11/2022

COGCC Comments

Comment	User	Date
1105.e. Abandonment in place requirements. For a flowline or crude oil transfer line abandoned in place, the operator must: (1). Evacuate the flowline or crude oil transfer line of any hydrocarbons or produced water to ensure the line is safe and inert; (2). Deplete the flowline or crude oil transfer line to atmospheric pressure; (3). Cut the flowline's or crude oil transfer line's risers to three (3) feet below grade or to the depth of the flowline or crude oil transfer line, whichever is shallower; (4). Seal the ends of the flowline or crude oil transfer line below grade; This is a partial rule description; all applicable rules are outlined in COGCC 1105. ABANDONMENT	maclarej	10/03/2022
Note: All Corrective Actions outlined on COGCC reclamation inspection Doc #682504203 submitted on 11/21/2018 that have not been addressed are still applicable.	maclarej	10/03/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403188570	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878820
690103221	Incomplete abandonment of flowline; misc debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878812
690103223	Flowline riser; view west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878813