

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE-66S92W /20NESW

Location ID: 322510



Photo #8059 From entrance to location.



Photo #8060 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE-66S92W /20NESW

Location ID: 322510



Photo #8061 Location lacks stabilization.



Photo #8062 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE-66S92W /20NESW

Location ID: 322510



Photo #8063 Location lacks stabilization.



Photo #8064 Insufficient tracking BMP at entrance to location.