

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/12/2022

Submitted Date:

10/14/2022

Document Number:

690203496

FIELD INSPECTION FORM

Loc ID 324797 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
JAMES STEVEN D		steve@westernoperating.com	
Kosola, Jason		jason.kosola@state.co.us	
Hart, Dale		dale@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212663	WELL	SI	01/01/2022	OW	061-06023	DAWSON A 1	RI

General Comment:

This is a follow up of the previous reclamation inspection #690203289.
See attached photos and additional details within this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
Crude Oil				
Comment:	Remediation project: 20712 is currently in process. There was previous spills that had occurred downhill from the tank battery. This impacted area has been excavated with some areas excavated deeper than other areas. There are still areas of oil stained soil at the surface that need to be cleaned up. Additional excavation is needed to remove contaminated soils.			
Corrective Action:	Clean up and remove stained soils per Rule 912.a. Properly dispose of oily waste in accordance with 905.e.			Date:

In Containment: Yes

Comment:

Multiple Spills and Releases?

Fencing/:				
Type	LOCATION			
Comment:	The electric fence around the location has been improved with insulators. The fence will need to be maintained to prevent livestock entry.			
Corrective Action:				Date:

Equipment:				corrective date
Type:		#		
Comment:	The tank battery and containment will need to be reinstalled per Rule 603.k., 603.o.			
Corrective Action:				Date:

Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Remediation project: 20712 is currently in process. All disturbed areas will need to be reclaimed per 1003 Rules.

Corrective Action Date _____

Overall Interim Reclamation _____ Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: There have been wattles installed along the west edge of the disturbance. Wattles should be trenched into the ground and properly staked. Additional BMP's also should be installed at the tank battery location to prevent sediment movement into the vegetation shown at photo 5. The berms around the impacted soil piles have been constructed larger but were not compacted. A liner should have been used underneath the impacted material storage. Additional BMP's need to be installed.</p>						
<p>Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C</p>						Date: <u>10/21/2022</u>
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203497	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886741