

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in multiple spots next to the well needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	10/20/2022
Type	TRASH		
Comment:	Trash next to the well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Plunger Lift		# 1		
Comment:				
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	Appears to be plumbed to surface			
Corrective Action:			Date:	
Other		#		
Comment:	Mechanical conditions on master valve needs repaired or replaced. See attached photo.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	10/20/2022

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 455180 Type: WELL API Number: 123-46914 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/04/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 10/10/22 at approximately 0937hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte P-T-28HNC of Civitas, at API # 05-123-46914 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Trash next to the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 10/20/22. Stained soil in multiple spots next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 10/20/22. Mechanical conditions on master valve needs repaired or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 10/20/22. See attached photos. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	10/11/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403193921	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883247
699106147	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883240