

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/13/2022

Submitted Date:

10/18/2022

Document Number:

700200081

FIELD INSPECTION FORM

Loc ID 335918 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8840
Name of Operator: BLUE CHIP OIL INC
Address: 155 E BOARDWALK DR STE 400
City: FORT COLLINS State: CO Zip: 80525

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspection@pdce.com	ALL INSPECTIONS
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
,		bluechipoil@msn.com	All Inspections

General Comment:

[This inspection was the result of Fire on plugging operation on location see Inspector comments for summary](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other	#		corrective date
Comment: transfer pump damaged by fire			
Corrective Action: remove and replace pump and move pump to safe distance from possible venting gases from tanks test and assure proper grounding			Date: 10/14/2022
Type: Other	#		
Comment: open top tank with gas buster			
Corrective Action: remove damaged tanks and move tanks from possible ignition sources insure and test for proper grounding			Date: 10/14/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

COGCC Comments

Comment	User	Date
<p>this is a follow up inspection to inspection document#700200077</p> <p>On Thursday, October 12, 2022 at 08:15 Hrs, I, conducted an on-site inspection at: Stonehocker location in Adams County Operated by: Blue Chip Oil Inc While there I observed: A plugging operation on location being conducted by Ensign supervised by PDC Energy on behave of Blue Chip Oil company. I spoke to PDC staff and Ensign staff who indicated they had a fire on location on 10-11-2022 at approx1600hrs. The rig operator from Ensign indicated he heard the pump on location start to take off and he saw a flash fire at the pump which was shutdown immediatley, but the fire travelled NW to the open top tank which was located approx 50' ton 60' from the pump. The fire was extinguished by the responding fire department using foam and water. There were no injuries and the only equipment damaged was the pump and the tank (see attached photos). Possible compliance issues observed: Upon inspection it appeared as the front of the tank was only approx 50 to 60' from the pump which was the cause of the flash fire. Several of the grounding rods did not appear to have proper grounding or depth for proper grounding of equipment. Weather: Skies: Partly Cloudy, Wind: Calm, Corrective Action Dialogue: Remove and replace damaged equipment and move tanks futher from possible ignition sources This is a summary of the inspection report</p>	gomezj	10/18/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700200082	location photos of damaged equipment from fire	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5889406