

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403193651

Date Received:

10/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

FarmingtonRegulatoryTechs@hilcorp.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500500

Inspection Date: 09/28/2022

FIR Submit Date: 09/28/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326474

Location Name: TENORIO-N35N8W Number: 32NWSE County: LA PLATA

Qtrqr: NWSE Sec: 32 Twp: 35N Range: 8W Meridian: N

Latitude: 37.256470 Longitude: -107.765050

FACILITY - API Number: 05-067- -00 Facility ID: 216553

Facility Name: TENORIO Number: 3-32

Qtrqr: NWSE Sec: 32 Twp: 35N Range: 8W Meridian: N

Latitude: 37.256470 Longitude: -107.765050

CORRECTIVE ACTIONS:

1 ☒ CA# 164830

Corrective Action: Remove oily residue and impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 10/13/2022

Response: CA COMPLETED

Date of Completion: 10/10/2022

Operator Comment: Remove oily residue and impacted material around the PU and dispose of the contaminated soil. Treated the area with Simple Green. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500500 has been satisfactorily completed, pending reinspection.

2 ☒ CA# 164831

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 10/13/2022

Response: CA COMPLETED

Date of Completion: 10/10/2022

Operator Comment: Rig anchors are marked properly. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500500 has been satisfactorily completed, pending reinspection.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 10/11/2022 11:14:18 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403193651	FIR RESOLUTION SUBMITTED
403193653	TENORIO 3-32 Resolved Photos

Total Attach: 2 Files