

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403199495

Date Received:

10/17/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 25250
Name of Operator: DUGAN PRODUCTION CORP

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-0420

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|-------------------------|---------------------|---|
| <u>Smaka, Kevin</u> | <u>505-325-1821</u> | <u>kevin.smaka@duganproduction.com</u> |
| <u>Labowskie, Steve</u> | | <u>steve.labowskie@state.co.us</u> |
| <u>Heslop, Jason</u> | | <u>jason.heslop@duganproduction.com</u> |
| <u>Foutz, Marty</u> | | <u>marty.foutz@duganproduction.com</u> |
| <u>Alexander, John</u> | | <u>john.alexander@duganproduction.com</u> |
| <u>Wheeler, Cody</u> | | <u>cody.wheeler@duganproduction.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500365

Inspection Date: 08/30/2022

FIR Submit Date: 08/31/2022

FIR Status: _____

Inspected Operator Information:

Company Name: DUGAN PRODUCTION CORP

Company Number: 25250

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-0420

LOCATION - Location ID: 325498

Location Name: TIFFANY-N32N7W Number: 11NENW County: LA PLATA

Qtrqtr: NENW Sec: 11 Twp: 32N Range: 7W Meridian: N

Latitude: 37.035760 Longitude: -107.581670

FACILITY - API Number: 05-067- -00 Facility ID: 214894

Facility Name: TIFFANY Number: 1

Qtrqtr: NENW Sec: 11 Twp: 32N Range: 7W Meridian: N

Latitude: 37.035760 Longitude: -107.581670

CORRECTIVE ACTIONS:

1 ☒ CA# 164241

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 09/30/2022

Response: CA COMPLETED

Date of Completion: 10/17/2022

Operator Comment: Diminished berm height on eastern edge of secondary containment has been corrected. Extension granted by inspector until 10/24/22.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500365 has been satisfactorily completed, pending reinspection.

5 ☒ CA# 164245

Corrective Action: Maintain access road and location conditions per rule 1002.f(2)F. Emergency vehicles must be able to access location in inclement weather conditions.

Date: 09/16/2022

Response: CA COMPLETED

Date of Completion: 10/17/2022

Operator Comment: Access road and location ruts have been repaired. Extension granted by inspector until 10/24/22.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500365 has been satisfactorily completed, pending reinspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyra M. Feil

Signed:

Title: Engineering Assistant

Date: 10/17/2022 3:04:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--|
| 403199495 | FIR RESOLUTION SUBMITTED |
| 403199503 | Document 702500365 photos - Diminished berm and access road repairs. |

Total Attach: 2 Files