

Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Signs/Marker:

CONTAINERS: Propane Tank needing labeling:

Before:



Propane tank lacking labeling


After:



Labels attached.

Tank Labels/Placards:

Before:



Tanks lacking information

After:



Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Signs/Marker (cont):

Wellhead: Lacking API number (API number is on sign) and access road information.

Before: (API number is on the sign, lacking road info)



After:

New sign w/API & road info.



Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Good Housekeeping:

Random debris:

Before:



Debris

After:



Picked up can.

Before:



Debris

After:



Picked up debris.

Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Good Housekeeping (cont):

Other: Guard missing from pump jack

Before:



Guard missing

Other: Random Staining

Before:



Staining

After:



After:



Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Good Housekeeping (cont):


Other: Random Staining

Before:



Staining

After:



Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Before:



Staining

After:



Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Good Housekeeping (cont):

Other: Random Staining

Before:



Staining



Staining

After:



Soil picked up, replaced with clean soil.

Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Good Housekeeping (cont):

Other: Random Staining

Before:



Staining

After:



Soil picked up, replaced with clean soil.



Dry Creek 1-14

API 05-107-06140

Response to COGCC Field Insp 700704570 dated 09/15/2022



ROBERT L BAYLESS
PRODUCER LLC

Good Housekeeping (cont):

Other: Load lines missing caps/plugs

Before: (no photo provided)

After:

