

GOLDEN EAGLE 35-05 API# 05-071-08419 – OGRIS OPERATING  
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 26, 2022  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690203391



PHOTO 1 & 2: MAINTENANCE HAS BEEN PERFORMED TO THE ACCESS ROAD TO CORRECT ERROSION CHANELS AND VEHICLE RUTTING. THE DIVERSION DITCHES ALONG THE ROAD SIDE HAVE BEEN REDEFINED AND CHECK DAMS ADDED TO PROPERLY SLOW AND DIVERT STORMWATER.

GOLDEN EAGLE 35-05 API# 05-071-08419 – OGRIS OPERATING  
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 26, 2022  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690203391



GOLDEN EAGLE 35-05 API# 05-071-08419 – OGRIS OPERATING  
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 26, 2022  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690203391



PHOTO 3: A CULVERT HAS BEEN ADDED ON THE MAIN ACCESS, CLIMBING ABOVE THE COMPRESSOR LOCATION. ROAD MATERIAL WAS ADDED ALONG THE MAIN ACCESS, THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND PROPERLY DIRECT SURFACE RUN OFF.

GOLDEN EAGLE 35-05 API# 05-071-08419 – OGRIS OPERATING  
COGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 26, 2022  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690203391



PHOTO 4: ROAD MATERIAL HAS ALSO BEEN ADDED TO THE LOCATION ACCESS AND IT HAS BEEN CROWNED TO ENCOURAGE SHEET FLOW AND DIRECT SURFACE RUN OFF TO THE ROCKED DIVERSION DITCH. THE CULVERT INLET HAS ALSO BEEN CLEANED AND RESET.