

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403184398

Date Received:
10/01/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800736
Inspection Date: 09/15/2022 FIR Submit Date: 09/30/2022 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 450973

Location Name: Walden Land Treatment Facility Number: T7-P18 County: _____
Qtrqtr: NENE Sec: 18 Twp: 9N Range: 78W Meridian: 6
Latitude: 40.755970 Longitude: -106.186010

FACILITY - API Number: 05-057-00 Facility ID: 450973

Facility Name: Walden Land Treatment Facility Number: T7-P18
Qtrqtr: NENE Sec: 18 Twp: 9N Range: 78W Meridian: 6
Latitude: 40.755970 Longitude: -106.186010

CORRECTIVE ACTIONS:

2 ☒ CA# 164876

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 10/15/2022

Response: CA COMPLETED Date of Completion: 09/30/2022

Operator Comment: Stormwater work has been completed on all location. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

Photos attached to this FIRR appear to show berm repair. Photos also appear to show soils of the berm are loose and unconsolidated and may now act as a sediment source. BMPs to minimize erosion of loose unprotected soils and to minimize offsite sediment transport not observed in attached photos.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 10/1/2022 3:11:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403184398	FIR RESOLUTION SUBMITTED
403184402	Stormwater maintained PIC

Total Attach: 2 Files