

FORM
INSPRev
X/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2022

Submitted Date:

11/08/2022

Document Number:

693701033

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: ALLISON, RICK On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10312
 Name of Operator: PROSPECT ENERGY LLC
 Address: 1036 COUNTRY CLUB ESTATES DR
 City: CASTLE ROCK State: CO Zip: 80108

Findings:

- 1 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Cam Gracey		graceyservices@msn.com	
Ward Giltner		wgiltner@yahoo.com	
Mary Griggs		griggs.mary@comcast.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483137	SPILL OR RELEASE	AC			-	MSSU 19-5 inj well flowline	EI

General Comment:

Inspected Facilities

Facility ID: 483137 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC followup Inspection of spill on the MSSU 19-5 injection flowline.

COGCC Staff met Operator personnel to witness confirmation soil sampling and collect split soil samples from select sample locations. COGCC collected three soil samples from excavation at flowline failure point, and three soil samples from impacted surface area. Operator has scraped impacted surface material to a depth of approximately 12-24" varying across the area and removed the impacted material prior to sampling. No soil stockpiles were present at the location.

Operator has submitted a Form 19 Supplemental Report. Operator will adhere to the Conditions of Approval in the Form 19 Supplemental Report, and submit a followup Form 19 Supplemental Report no later than 90 days after the the Spill discovery date pursuant to Rule 912.b.(6).

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701034	Surface impacted area looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908289
693701035	Surface impacted area looking southwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908290
693701036	Surface impacted area looking southeast	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908291