

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2022

Submitted Date:

11/03/2022

Document Number:

696204286**FIELD INSPECTION FORM**Loc ID 412922 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments5 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		Heather.Lang@oxbow.com	
		Tyson.Johnston@oxbow.com	
		geops@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412922	LOCATION	AC			-	DGU Federal 1289 17-11 Pad	RI
436561	WELL	AL	11/01/2018	LO	051-06123	DGU Federal 1289 17-11 CS2	AL

General Comment:

On 11/1/2022, Reclamation Specialist Trujillo, and Reclamation Supervisor Arthur inspected Gunnison Energy's DGU Federal 1289 17-11 pad location in Gunnison County, Colorado.

This inspection is a followup to #696202043 and #696203553 to document compliance with the following corrective actions:

- §34-60-121(1)(a), C.R.S.: Form 4 condition requirements- Signage
- Plugging and abandonment of conductor.

It was observed that this Location remains out of compliance with COGCC Rules and corrective actions

The following new compliance issues were observed per this inspection:

- Location Signage
- Protection of stockpiled soils.
- Anchors improperly marked.

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	It was observed in this inspection that the Location signage at the entrance of the Location has been removed.		
Corrective Action:	Install Location signage.	Date:	12/01/2022
Type	OTHER		
Comment:	Pursuant to conditions within the 502.b Delayed Interim Reclamation NTO document #401463219, Operator was required to post a sign at the location entrance stating the following: "A COGCC variance has been approved to delay the commencement of interim reclamation to no later than December 9, 2022". It was observed that a sign has been placed at the Location entrance, however sign has not been properly secured and is now considered debris. Sign is also made of poor quality material and is showing sign of deterioration.		
Corrective Action:	Maintain Delayed Interim Reclamation NTO signage.	Date:	11/10/2022

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	412922	Type:	LOCATION	API Number: -	Status:	AC	Insp. Status:	RI	
Facility ID:	436561	Type:	WELL	API Number:	051-06123	Status:	AL	Insp. Status:	AL

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

Soil stockpiles observed on the north end of the Location. BMPs to protect stockpiles from wind and water erosion, as well as to minimize erosion, degradation and sediment transport are missing or insufficient.

Corrective Action _____

Comply with Rule 1002.c and 1002.f.

Date **11/10/2022**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Markers at anchors have not been maintained in a proper condition.

Corrective Action _____

Maintain markers.

Date **11/18/2022**

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Operator received a 502.b Delayed Interim Reclamation variance. See Sundry #401463219 for additional details; variance expires 12/9/2022; interim reclamation work on the Location is required to be completed by 12/9/2022. A followup inspection will be conducted to document compliance with 1003 rules and Sundry Conditions of Approval.

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Previous inspections observed that the conductor for the abandoned well API #05-051-06123 has not been plugged and reclaimed per Rule 406 Requirements. Inspection required Operator to comply with Rule 406.e.(4).

It was observed in this inspection that the conducted and related cellar have been removed, however no Form 4 "Report of Work Done, Other: Plugged Conductor for the Oil and Gas Location" to report the plugging of the conductor has been submitted. Corective action has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 406.e.(4)**

Date **05/31/2022**

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403219003	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905383
696204287	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905367