

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2022

Submitted Date:

11/03/2022

Document Number:

697006650**FIELD INSPECTION FORM**Loc ID 447046 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447047	TANK BATTERY	AC	07/29/2016		-	WERNING 01-02B,08-03B,41-03B	AC

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tanks #360876 and #360877 lack contents and capacity placards, methanol system requires new placards. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/30/2022
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Emission Control Device	# 2		
Comment:	Pilots are on, ECD's are anchored.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration card is current.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Anchored.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Automation array, methanol system in secondary containment, two ECD scrubbers.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	<100 BBLS	BV CONCRETE		,	
Comment: 60 bbls, anchored.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Lined berm				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	300 BBLS	STEEL AST		,	
Comment: Anchored.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Lined berm				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	447047	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 11/3/2022 at approximately 12:20 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Werning 01-02B, 08-03B, 41-03B Tank Battery location #447047 in Weld County, Colorado.</p> <p>While there, I observed that two crude oil tanks were missing contents/capacity placards and the methanol system required new placards. During this inspection the following possible compliance issues were observed: Rule 605.h. with a corrective action date of 12/30/2022.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	11/03/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403219002	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905382
697006651	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905372