

Document Number:  
 403173098  
 Date Received:  
 10/31/2022

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10633 Contact Name: Adam Conry  
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 883-3351  
 Address: 1801 CALIFORNIA STREET #2500 Fax: \_\_\_\_\_  
 City: DENVER State: CO Zip: 80202 Email: AConry@civiresources.com

**For "Intent" 24 hour notice required,** Name: Sherman, Susan Tel: (719) 775-1111  
**COGCC contact:** Email: susan.sherman@state.co.us

Type of Well Abandonment Report:  Notice of Intent to Abandon  Subsequent Report of Abandonment

API Number 05-005-06500-00  
 Well Name: STATE-SMITH Well Number: 1-16  
 Location: QtrQtr: NWNW Section: 16 Township: 4S Range: 65W Meridian: 6  
 County: ARAPAHOE Federal, Indian or State Lease Number: \_\_\_\_\_  
 Field Name: WILDCAT Field Number: 99999

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 39.709073 Longitude: -104.676053  
 GPS Data: GPS Quality Value: 0.0 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 10/26/1981  
 Reason for Abandonment:  Dry  Production Sub-economic  Mechanical Problems  
 Other \_\_\_\_\_  
 Casing to be pulled:  Yes  No Estimated Depth: \_\_\_\_\_  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	207	200	207	0	VISU
OPEN HOLE	7+7/8				207	8644				

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 95 sks cmt from 5700 ft. to 5500 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set 45 sks cmt from 3100 ft. to 3000 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set 80 sks cmt from 2026 ft. to 1826 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set 330 sks cmt from 1445 ft. to 588 ft. Plug Type: OPEN HOLE Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)

Set 75 sacks half in. half out surface casing from 275 ft. to 0 ft. Plug Tagged:

Set 20 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Number of Days from Setting Surface Plug  
Surface Plug Setting Date: 09/03/2022 Cut and Cap Date: 09/09/2022 to Capping or Sealing the Well: 6

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: Swabbco

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1105  Yes  No

Technical Detail/Comments:

- 1) Form 42 was submitted prior to plugging operations, Form 42 Doc #403145536 (MIRU) & Doc#403145535 (SOP)
  - 2) No fluids or gas migration was present prior to cement plug to surface being set. The plug was cemented to surface with 75 sacks of cement from 275'.
  - 3) Plug was cemented to surface and topped off w/ 20 sx at surface (Total sx 95).
  - 4) At least 100' of cement was left in the wellbore for each plug.
  - 5) This form 6-SRA addresses all COA's from the Form 6-NOIA.
- Attached to this form:
- a. Cement tickets are attached to this form.
  - b. Operations summary is attached to this form for reference.
  - c. Final P&A WBD is attached to this form.

Actual GPS data is unknown.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Ashley Noonan

Title: Sr Regulatory Analyst Date: 10/31/2022 Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 11/10/2022

CONDITIONS OF APPROVAL, IF ANY:

<b>COA Type</b>	<b>Description</b>
0 COA	

**Attachment List**

<b>Att Doc Num</b>	<b>Name</b>
403173098	FORM 6 SUBSEQUENT SUBMITTED
403173111	CEMENT JOB SUMMARY
403173113	OPERATIONS SUMMARY
403213612	OTHER
403213656	WELLBORE DIAGRAM

Total Attach: 5 Files

**General Comments**

<b>User Group</b>	<b>Comment</b>	<b>Comment Date</b>
		Stamp Upon Approval

Total: 0 comment(s)