

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402988976

Date Received:

03/18/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rowley, Darren

drowley@logosresourcesllc.com

regulatory@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903969

Inspection Date: 12/07/2021

FIR Submit Date: 12/08/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 325158

Location Name: BONDAD 33-9-N33N9W Number: 10NESE County: LA PLATA

Qtrqtr: NESE Sec: 10 Twp: 33N Range: 9W Meridian: N

Latitude: 37.115770 Longitude: -107.808230

FACILITY - API Number: 05-067- -00 Facility ID: 214157

Facility Name: BONDAD 33-9 Number: 11

Qtrqtr: NESE Sec: 10 Twp: 33N Range: 9W Meridian: N

Latitude: 37.115770 Longitude: -107.808230

CORRECTIVE ACTIONS:

1 ☒ CA# 158466

Corrective Action: -Long term stabilization measures need to be installed to stabilize erosional channeling and sedimentation along the access road by 1/15/2022.

Date: 01/15/2022

Response: CA COMPLETED

Date of Completion: 01/13/2022

Operator Comment: Long-term stabilization measures were installed to stabilize erosional channeling and sedimentation along the access road.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval of this form is an acknowledgement that the form is received and is not an approval of the corrective action response as further review or field inspection may be needed.

OPERATOR COMMENT AND SUBMITTAL

Comment: Long-term stabilization measures were installed to stabilize erosional channeling and sedimentation along the access road.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Marie E. Florez

Signed: _____

Title: Regulatory Specialist

Date: 3/18/2022 12:30:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402988976	FIR RESOLUTION SUBMITTED
402988992	Road repair 1
402988994	Road repair
402988998	well sign

Total Attach: 4 Files