

BMP Corrective Actions
Location Name: Eagle Hill 1-32
Location ID: 466705
API#: 057-06625

Undercut wattle repair. On 10/07/2022 EcoPoint personnel backfilled, compacted and surface roughened area to repair undercut wattle and avoid any potential for future rilling.

Photos 1-3: Undercutting on wattle repair.

