

ARKOMA OPERATIONS LLC

Well Name:	Hahn 1-A	API #	067-08112	Location ID #	311911
	IGE 100		067-09022		
	IGE 135		067-09346		
Inspector:	Alex Klink				
Date Inspected:	11/4/2022				
Date Submitted:	11/4/2022				
Document Number:	702500725				

Corrective Action 1:

Comment:	Berm height is diminished at produced water tanks (IMG 05).	
Corrective Action:	Repair/maintain berms or other secondary containment devices per Rule 603 o.	Date: 12/04/2022

Correction Action 1 Due: 12/4/2022

Action Completed: 11/11/2022

Action Taken: Repaired berm to appropriate height

BEFORE PHOTOS



IMG 05

Berm height is diminished

AFTER PHOTOS



Corrective Action 2:

Comment:	Erosion channel on southwest corner of location (IMG 03). Erosion channel at produced water tank (IMG 04). Stormwater BMP's not maintained.	
Corrective Action:	Install or repair/modify required BMPs per Rule 1002.f.(2)C	Date: 12/04/2022

Correction Action 1 Due:

12/4/2022

Action Completed:

11/11/2022

Action Taken:

Repaired erosion channel on the southwest corner of the location and channel at the produced water tank

BEFORE PHOTOS



IMG 03

Erosion channel on southwest corner of location



IMG 04

Erosion channel within secondary containment

AFTER PHOTOS

