

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403223505

Date Received:
11/09/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Etta Trujillo</u>	<u>505-324-4145</u>	<u>etrujillo@logosresourcesllc.com</u>
<u>Dacye Shull</u>	<u>505-787-2027</u>	<u>dshull@logosresourcesllc.com</u>
<u>Vanessa Fields</u>	<u>505-787-2218</u>	<u>vfields@logosresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203372

Inspection Date: 08/30/2022

FIR Submit Date: 09/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 325172

Location Name: BONDAD 33-9-N33N9W Number: 3NWSW County: LA PLATA

Qtrqr: NWS Sec: 3 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.130460 Longitude: -107.818340

FACILITY - API Number: 05-067- -00 Facility ID: 214194

Facility Name: BONDAD 33-9 Number: 5

Qtrqr: NWS Sec: 3 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.130460 Longitude: -107.818340

CORRECTIVE ACTIONS:

1 ☒ CA# 164544

Corrective Action: Per Rule 406.e., Operator needs to install wildlife/livestock protection around the wellhead cellar to prevent accidental access, by 11/30/2021.

Date: 11/30/2021

Response: CA COMPLETED

Date of Completion: 11/08/2022

installed wildlife/livestock protection around the wellhead cellar to prevent accidental access, Per Rule 406.e.

Operator
Comment:

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 164545

Corrective Action: COGCC accepts the submission of the stormwater plan however no approval will be provided since it is the Operator's responsibility to remain in compliance at all times regardless of a submitted plan. Stormwater management must be designed, implemented, and maintained according to good engineering practices which may require further actions beyond the scope of the plan.
Install or repair required BMPs per Rule 1002.f.(2)C

Date: _____

Response: CA COMPLETED

Date of Completion: 11/08/2022

Operator
Comment:

Installed required BMPs per Rule 1002.f.(2)C

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Installed wildlife/livestock protection around the wellhead cellar to prevent accidental access, Per Rule 406.e. Installed required BMPs per Rule 1002.f.(2)C

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dacye Shull

Signed: _____

Title: Regulatory Technician

Date: 11/9/2022 12:28:52 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403223505	FIR RESOLUTION SUBMITTED
403223535	Cellar Protection photo1
403223538	Cellar Protection photo 2
403223539	Cellar Protection photo

Total Attach: 4 Files