


TEP
Specialty 12C
Location # 335147



location



location

TEP
Specialty 12C
Location # 335147



location



ECD has been removed piping and knock out still in place

TEP
Specialty 12C
Location # 335147



location



location

TEP
Specialty 12C
Location # 335147



Lack of stabilization/ compaction



Lack of stabilization/ compaction

TEP
Specialty 12C
Location # 335147



Lack of stabilization/ compaction



Lack of stabilization/ compaction