

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403228898

Date Received:

11/14/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

General

FarmingtonRegulatoryTechs@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500763

Inspection Date: 11/09/2022

FIR Submit Date: 11/09/2022

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326511

Location Name: HUBER-BURKETT-N34N8W Number: 3SESW County: LA PLATA

Qtrqtr: SESW Sec: 3 Twp: 34N Range: 8W Meridian: N

Latitude: 37.239580 Longitude: -107.736720

FACILITY - API Number: 05-067-00 Facility ID: 89124

Facility Name: HUBER-BURKETT Number: 4-3

Qtrqtr: SESW Sec: 3 Twp: 34N Range: 8W Meridian: N

Latitude: 37.239580 Longitude: -107.736720

CORRECTIVE ACTIONS:

1 CA# 166024

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 11/17/2022

Response: CA COMPLETED

Date of Completion: 11/14/2022

Operator
Comment:

Impacted material from lube oil at wellhead has been removed and disposed of properly. See attached photos.

COGCC Decision: _____

| | | | |
|-----------------------|--|--|--|
| COGCC Representative: | | | |
|-----------------------|--|--|--|

| | | | |
|-----------------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| 2 | CA# 166025 | | |
| Corrective Action: | | All unused equipment must be returned to use or stored off location per rule 606. | Date: 11/24/2022 |
| Response: | | CA COMPLETED | Date of Completion: 11/14/2022 |
| Operator Comment: | | 1" pipe at separator, 5 gallon lube oil container at wellhead have been removed. 2" muffler exhaust hose at separator, See attached photos. | |
| COGCC Decision: _____ | | | |
| COGCC Representative: | | | |

| | | | |
|-----------------------|-------------------|----------------------------------------------------------|--------------------------------|
| 3 | CA# 166026 | | |
| Corrective Action: | | Install proper guy line markers per Rule 1003.a | Date: 11/24/2022 |
| Response: | | CA COMPLETED | Date of Completion: 11/14/2022 |
| Operator Comment: | | 4 of 4 anchors are marked properly. See attached photos. | |
| COGCC Decision: _____ | | | |
| COGCC Representative: | | | |

| | |
|-----------------------------------------------------------------------------------------------------------------------|-----------------------------|
| <u>OPERATOR COMMENT AND SUBMITTAL</u> | |
| Comment: | |
| I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete. | |
| Print Name: Priscilla Shorty | Signed: _____ |
| Title: OperationsRegulatory Tech | Date: 11/14/2022 3:35:23 PM |

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|-----------------|----------------------------------|
| 403228915 | Huber Burkett 4-3Resolved Photos |

Total Attach: 1 Files