

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403230456

Date Received:
11/15/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700704691

Inspection Date: 11/07/2022

FIR Submit Date: 11/09/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335504

Location Name: DIAZ-66S94W Number: 25SENE County: _____

Qtrqr: SENE Sec: 25 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.499672 Longitude: -107.829330

FACILITY - API Number: 05-045- -00 Facility ID: 335504

Facility Name: DIAZ-66S94W Number: 25SENE

Qtrqr: SENE Sec: 25 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.499672 Longitude: -107.829330

CORRECTIVE ACTIONS:

1 ☒ CA# 166030

Corrective Action: Remove debris

Date: 11/18/2022

Response: CA COMPLETED

Date of Completion: 11/15/2022

Operator
Comment:

Debris has been removed. Hose and wheel valve (belonging to Summit Midstream) have been removed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 166031

Corrective Action: Install or repair required BMPs

Date: 05/31/2021

Response: CA COMPLETED

Date of Completion: 11/15/2022

Operator Comment: This location is regularly bladed / dragged to control and maintain ruts. The location was dragged again today (11/15/22). The Production Supervisor has inspected this location and determined there is sufficient rock and base present on the working portion of the pad surface. The pad location and working surface are in good, stable condition. TEP will continue to inspect and maintain the working area and access to this pad / equipment as needed. See attached pics.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions at this location have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Environmental Lead

Date: 11/15/2022 4:44:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403230456	FIR RESOLUTION SUBMITTED
403230658	Photo
403230661	Photo
403230662	Photo
403230663	Photo
403230664	Photo
403230665	Photo

Total Attach: 7 Files