

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403191704

Date Received:

10/10/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Laramie

cogccnotifications@laramie-energy.com

Benjamin.Boudreaux@coag.gov

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203881

Inspection Date: 07/19/2022

FIR Submit Date: 07/22/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 312512

Location Name: Davis Dolley Number: 36-1 Pad County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 36 Twp: 9S Range: 95W Meridian: 6

Latitude: 39.239903 Longitude: -107.941169

FACILITY - API Number: 05-077- 00 Facility ID: 312512

Facility Name: Davis Dolley Number: 36-1 Pad

Qtrqtr: NWNE Sec: 36 Twp: 9S Range: 95W Meridian: 6

Latitude: 39.239903 Longitude: -107.941169

CORRECTIVE ACTIONS:

2 ☒ CA# 163493

Corrective Action: Comply with 1004 rules and complete reclamation. Implement best management practices and strategies to ensure site progresses towards COGCC 1004 requirements, including an 80% uniform, desirable perennial revegetation standard. Conduct ongoing monitoring/management efforts until site receives a passing final reclamation inspection. A CA date of 11/15/2022 is being provided to allow operator to implement initial weed management strategies prior to reclamation efforts.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 10/08/2022

Operator Comment: DCP required us to stay 15ft on either side of their pipeline ROW, so there is 30ft that could not be completed. The area is also very rocky, so we went as deep as we could. Updated Pictures for most recent work completed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Based on Operator comments it is unclear if reclamation work has been completed in accordance with 1004 requirements. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: More work was done for reclamation of Pad.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 10/10/2022 8:22:09 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403191704	FIR RESOLUTION SUBMITTED
403191706	Pad Photos

Total Attach: 2 Files