

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403195420

Date Received:  
10/12/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 760 HORIZON DRIVE STE 400  
City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Gas_UtahGasCorp</u>	<u>970-693-6021</u>	<u>inspections@utahgascorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204020  
Inspection Date: 08/25/2022 FIR Submit Date: 08/29/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP Company Number: 10539  
Address: 760 HORIZON DRIVE STE 400  
City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 322317

Location Name: FEDERAL-CARBONERA-67S104W Number: 2NWNW County: \_\_\_\_\_  
Qtrqtr: NWN Sec: 2 Twp: 7S Range: 104W Meridian: 6  
W  
Latitude: 39.486663 Longitude: -108.963042

FACILITY - API Number: 05-045-00 Facility ID: 322317

Facility Name: FEDERAL-CARBONERA-67S104W Number: 2NWNW  
Qtrqtr: NWN Sec: 2 Twp: 7S Range: 104W Meridian: 6  
W  
Latitude: 39.486663 Longitude: -108.963042

CORRECTIVE ACTIONS:

1  CA# 164178

Corrective Action: Comply with 1002.f.; Implement and maintain BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation on access road. Ensure controls are implemented in accordance with good engineering practices and maintained in proper functioning condition; regrading alone will not be sufficient to stabilize road and manage runoff.

Date: 09/13/2022

Response: CA COMPLETED Date of Completion: 10/11/2022

Operator Comment: Erosion repairs complete

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, erosion issues appear to have been repaired, however it is unclear what BMPs, if any, have been implemented to minimize further erosion, degradation and sediment transport. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tami Dahl

Signed: \_\_\_\_\_

Title: Production Tech

Date: 10/12/2022 1:41:55 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403195420	FIR RESOLUTION SUBMITTED
403195428	Erosion 1
403195431	Location 2
403195437	Location

Total Attach: 4 Files