

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403204386

Date Received:
10/21/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203898

Inspection Date: 07/27/2022

FIR Submit Date: 07/29/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 479149

Location Name: BJU Number: B26-496 County: _____
Pad

Qtrqtr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.677052 Longitude: -108.138400

FACILITY - API Number: 05-045- -00 Facility ID: 479149

Facility Name: BJU Number: B26-496
Pad

Qtrqtr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.677052 Longitude: -108.138400

CORRECTIVE ACTIONS:

2 CA# 163646

Corrective Action: Comply with Rule 1002.f and implement perimeter stormwater and erosion control BMPs to manage runoff, and to allow for sediment laden-free discharge from the Location; ensure BMPs are installed accordance with good engineering practices, are adequate for the sites conditions, and are maintained in a proper functioning conditions. Ensure stockpiled topsoil is not incorporated with the BMPs, and remain protected.

Date: 09/10/2021

Response: CA COMPLETED Date of Completion: 10/05/2022

Installed earth berm and wattles segregating topsoil from subsoils. Hydro seeded and mulched topsoil. See

Operator photo.
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 10/21/2022 6:33:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403204386	FIR RESOLUTION SUBMITTED
403204387	Wattles installed to protect topsoil

Total Attach: 2 Files