

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403206896

Date Received:
10/25/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203992

Inspection Date: 08/17/2022

FIR Submit Date: 08/22/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 479214

Location Name: BJU N23-496 Central Delivery Point Number: Production Pad County: _____

Qtrqtr: SESW Sec: 23 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.680578 Longitude: -108.138397

FACILITY - API Number: 05-045-00 Facility ID: 479214

Facility Name: BJU N23-496 Central Delivery Point Number: Production Pad

Qtrqtr: SESW Sec: 23 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.680578 Longitude: -108.138397

CORRECTIVE ACTIONS:

1 ☒ CA# 164019

Corrective Action: Install signage/labeling at battery/tanks.

Date: 08/17/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Sign was installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 164020

Corrective Action: Comply with Rule 1002.f, 1002.b and 1002.c; implement perimeter stormwater and erosion control BMPs to manage runoff, and to allow for sediment laden-free discharge from the Location; ensure BMPs are installed accordance with good engineering practices, are adequate for the sites conditions, and are maintained in a proper functioning conditions. Ensure stockpiled topsoil is not incorporated with the BMPs, and remain protected.

Date: 09/10/2021

Response: CA COMPLETED

Date of Completion: 10/21/2022

Operator Comment: Conducted interim reclaim, installed bmps, and seeded and mulched.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 164021

Corrective Action: Comply with Rules 1002.c and 1002.f.

Date: 07/01/2022

Response: CA COMPLETED

Date of Completion: 10/21/2022

Operator Comment: BMPs were installed, location was seeded and mulched.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 10/25/2022 6:53:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403206896	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files