

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402994060

Date Received:
03/24/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Bill Espinosa</u>	<u>303-829-4982</u>	<u>billespinosa30@yahoo.com</u>
<u>Ingve, Ed</u>	<u>(303) 829-2354</u>	<u>ed@renegadeoilandgas.com</u>
<u>JB Condill</u>	<u>303-680-4725</u>	<u>jbcrog@aol.com</u>
<u>Canfield, Chris</u>		<u>chris.canfield@state.co.us</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700900913
Inspection Date: 11/18/2021 FIR Submit Date: 11/18/2021 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 319999

Location Name: UPRR 48 PAN AM H-62S63W Number: 25SESE County: ADAMS
Qtrqtr: SESE Sec: 25 Twp: 2S Range: 63W Meridian: 6
Latitude: 39.841520 Longitude: -104.378840

FACILITY - API Number: 05-001-00 Facility ID: 202201

Facility Name: UPRR 48 PAN AM H Number: 1
Qtrqtr: SESE Sec: 25 Twp: 2S Range: 63W Meridian: 6
Latitude: 39.841520 Longitude: -104.378840

CORRECTIVE ACTIONS:

1 CA# 157968

Corrective Action:

Date: 11/03/2021

Appears that the operator has removed vault in berm on the south side for tanks. Appears to have stained soil in open hole and in the dirt that was removed. COGCC Rule 1002. is not being followed, and there appears to be no BMPs in place - fencing around open hole, proper storage of dirt that appears to have stained soil in it, No storm water management of removed soil and around the removed vault. Corrective action date 12/3/2021 see photos 5 through 23.

Response: CA COMPLETED

Date of Completion: 11/23/2021

Operator Comment: Form 27 (Document No. 402614862) has been filed for this project on 3/4/2021. The previous operator improperly closed/buried a historical cement vault at the well's tank battery. Working with the COGCC to remediate this pit closure to satisfy any requirements. Circumstances have become vastly more involved than was first anticipated.

COGCC Decision: Approved

COGCC Representative:

2 CA# 157969

Corrective Action: Stained soil around well head. Control and contain spills/releases and clean up per Rule 905.e. Corrective Action Date 12/10/2021 to remove stained soil. See attached photo #4

Date: 12/10/2021

Response: CA COMPLETED

Date of Completion: 11/23/2021

Operator Comment: Stained soil and weeds around wellhead addressed.

COGCC Decision: Approved

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Form 27 (document no. 402614862) has been filed for tank battery area on 3/4/2021. The scope of the project and work could not of been anticipated.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: _____

Title: Manager/Owner

Date: 3/24/2022 11:41:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402994060	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files