

Lemon L1

Document number 702500718

Date completed 11/16/2022

Erosion channels and ruts in road repaired



Drainage ditch around location was reestablished



Erosion channels repaired and sediment removed



Additional channeling repaired
Cobble added to existing channel to help mitigate erosion



Erosion channel repaired
Sediment removed and drainage berm installed

