

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2022

Submitted Date:

11/21/2022

Document Number:

702800949

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
433805 \_\_\_\_\_ O'Malley, Anna \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10396  
Name of Operator: SWN PRODUCTION COMPANY LLC  
Address: P.O. BOX 12359  
City: SPRING State: TX Zip: 77391-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 14 Number of Comments  
5 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gee, Elizabeth	(832) 796-2873	liz_gee@swn.com	<a href="#">All Inspections</a>
Pate, James		jspconcrete@yahoo.com	<a href="#">All Inspections</a>
Galloway, Kelly		kgallowaywerc@gmail.com	<a href="#">All Inspections</a>
Stepp, Sarah		wccassistant@gmail.com	<a href="#">All Inspections</a>

**General Comment:**

On 11/16/2022, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at Beeman Oil & Gas Inc's Bulldog /22-41V-890 Location #433805 in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Wellhead sign lacks API #
- Tank battery sign lacks API #
- Vegetation and vegetation debris present around equipment
- Noxious Weeds
- Stormwater BMPs not maintained

Refer to the "Location," "Reclamation," "Stormwater" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Previous inspection #702800166 observed signs with incorrect Operator information. Signs have been updated with current Operator information, This corrective action has been addressed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s); no API number.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/20/2023
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at battery; no API number.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	01/20/2023

<b>Emergency Contact Number:</b>			
Comment:	(970) 210-2896 911		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	Previous inspection #702800166 observed wildlife protection devices to prevent wildlife from entering secondary containment BMPs were missing/insufficient. This corrective action has been addressed.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? **Fail**

Comment **Vegetation is established within and around equipment throughout the Location. There is no evidence this corrective action has been addressed. Corrective action and date from inspection #692402719 remain applicable.**

Corrective Action **Remove vegetation from equipment areas.** Date **12/18/2020**

Unused or unneeded equipment onsite? **Pass**

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment **Previous inspection #692402719 observed: Open casing/rat hole, adjacent to wellhead allows wildlife ingress with no means of egress and is workplace safety hazard. Inspector required Operator to cover/or close open casing to maximize safety and wildlife welfare.  
It was observed in this inspection that the open casing/rat hole adjacent to the wellhead has been covered with a steel plate. This corrective action has been addressed.**

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? **Pass**

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ F \_\_\_\_\_

Comment 
 Previous inspection #689804400 observed B List Noxious Weeds growing in vegetated areas. Inspector required Operator to "control noxious and debris weeds; commencement of controls in Spring of 2021 sheduled as indicated by monitoring." Inspection #689804400 also observed noxious weeds and undesirable plant species.  
  
 It was observed in this inspection that noxious weeds and undesirable plant species are widespread. There is no evidence of weed management. Original corrective action and date remain applicable. Weed management required in the 2023 growing season.  
  
 After review of this location with Enforcement, it was determined that per Approved Variance document #401291901, interim reclamation is required by 11/15/2023.

Corrective Action Comply with Rule 1003.f and conduct weed management on the Location. Date 06/20/2021

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
 Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
 Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
 Gravel removed \_\_\_\_\_  
 Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
 Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
 Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
 Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection #702800166 observed that the Location perimeter berm to manage stormwater was not maintained in proper functioning condition. Due to wildlife burrowing and extensive livestock hoof action the berm has been compromised.  
It was observed in this inspection that the perimeter stormwater berm remains degraded and compromised. Original corrective action and date remain applicable.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Ensure control measures are adequate for the sites conditions, have been installed in accordance with good engineering practices, and are maintained in proper functioning condition.

Date: 06/03/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702800952	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5922440">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5922440</a>