

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: [Sign has faded and is illegible, see attached photo.](#)

Corrective Action: [Install sign to comply with Rule 605.d.](#)

Date: 02/24/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment: Bradenhead valve is exposed at surface.				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Tank battery #452963				
Corrective Action:				Date:	

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 243537 Type: WELL API Number: 123-11329 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 11/17/2022 at approximately 12:05 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KPK Lorenz 1-D API #123-11329 in Weld County, Colorado. While there, I observed that the wellhead sign had faded and was illegible. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 2/24/2023. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	11/17/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403233436	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918444
697006721	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5918434