

Document Number:  
403240334

Date Received:  
11/28/2022

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10677 Contact Name: Richard Murray

Name of Operator: WOLVERINE RESOURCES LLC Phone: (907) 989-3092

Address: 109 EAST 17TH STREET #430 Fax: \_\_\_\_\_

City: CHEYENNE State: WY Zip: 82001 Email: g.richard.murray@state.co.us

**For "Intent" 24 hour notice required,** Name: Scott Ramsey Tel: (970) 623-9782

**COGCC contact:** Email: scott.ramsey@state.co.us

Type of Well Abandonment Report:  Notice of Intent to Abandon  Subsequent Report of Abandonment

API Number 05-081-07304-00

Well Name: ANDERSON (OWP) Well Number: 31-32

Location: QtrQtr: NWNE Section: 32 Township: 10N Range: 93W Meridian: 6

County: MOFFAT Federal, Indian or State Lease Number: \_\_\_\_\_

Field Name: GREAT DIVIDE Field Number: 32750

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.787871 Longitude: -107.857999

GPS Data: GPS Quality Value: 1.6 Type of GPS Quality Value: \_\_\_\_\_ Date of Measurement: 02/15/2007

Reason for Abandonment:  Dry  Production Sub-economic  Mechanical Problems

Other Orphan Well Program

Casing to be pulled:  Yes  No Estimated Depth: 7959

Fish in Hole:  Yes  No If yes, explain details below

Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below

Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
LEWIS	7558	7642			

Total: 1 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
CONDUCTOR	24	16	UK	UK	0	40				
SURF	12+1/4	8+5/8	UK	UK	0	817	380	817	0	
1ST	7+7/8	5+1/2	UK	UK	0	7951	742	7951	4270	

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7508 with 3 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 24 sks cmt from 6840 ft. to 6620 ft. Plug Type: ANNULUS Plug Tagged:   
Set 12 sks cmt from 6000 ft. to 5900 ft. Plug Type: ANNULUS Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at 4050 ft. with 37 sacks. Leave at least 100 ft. in casing 4000 CICR Depth  
Perforate and squeeze at 2652 ft. with 37 sacks. Leave at least 100 ft. in casing 2602 CICR Depth  
Perforate and squeeze at 867 ft. with 37 sacks. Leave at least 100 ft. in casing 817 CICR Depth  
(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged:

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_  
Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105  Yes  No

Technical Detail/Comments:

Pug 7  
Circulate 15 sx w/returns to surface  
Establish circulation to surface  
Perf 5-1/2" @ 50'

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Richard Murray

Title: OWP Specialist Date: 11/28/2022 Email: g.richard.murray@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

Expiration Date: \_\_\_\_\_

<u>COA Type</u>	<u>Description</u>
0 COA	

**Attachment List**

<u>Att Doc Num</u>	<u>Name</u>
403241293	WELLBORE DIAGRAM

Total Attach: 1 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)