

FORM

6

Rev
11/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:

403240880

Date Received:

11/28/2022

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10677

Contact Name: Richard Murray

Name of Operator: WOLVERINE RESOURCES LLC

Phone: (970) 989-3092

Address: 109 EAST 17TH STREET #430

Fax:

City: CHEYENNE State: WY Zip: 82001

Email: g.richard.murray@state.co.us

For "Intent" 24 hour notice required,

Name: Ramsey, Scott

Tel: (970) 623-9782

COGCC contact:

Email: scott.ramsey@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-081-07288-00

Well Name: ELLIS (OWP)

Well Number: 44-30

Location: QtrQtr: SESE Section: 30 Township: 10N Range: 93W Meridian: 6

County: MOFFAT

Federal, Indian or State Lease Number:

Field Name: GREAT DIVIDE

Field Number: 32750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.792650

Longitude: -107.868780

GPS Data: GPS Quality Value: 1.7 Type of GPS Quality Value: Date of Measurement: 04/03/2012

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☒ Other Orphan Well ProgramCasing to be pulled: ☐ Yes ☒ No Estimated Depth: 9110Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☒ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
LEWIS	7469	7714			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
CONDUCTOR	20	16	UK	Uk	0	40				
SURF	12+1/4	8+5/8	UK	24	0	806	380	806	0	
1ST	7+7/8	5+1/2	UK	17	0	7994	485	7994	4670	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7418 with 3 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>15</u> sks cmt from <u>7000</u> ft. to <u>6900</u> ft.	Plug Type: <u>ANNULUS</u>	Plug Tagged: <input type="checkbox"/>
Set <u>15</u> sks cmt from <u>6810</u> ft. to <u>6710</u> ft.	Plug Type: <u>ANNULUS</u>	Plug Tagged: <input type="checkbox"/>
Set <u>15</u> sks cmt from <u>5570</u> ft. to <u>5470</u> ft.	Plug Type: <u>ANNULUS</u>	Plug Tagged: <input type="checkbox"/>
Set <u>15</u> sks cmt from <u>4800</u> ft. to <u>4700</u> ft.	Plug Type: <u>ANNULUS</u>	Plug Tagged: <input type="checkbox"/>
Set _____ sks cmt from _____ ft. to _____ ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at 2550 ft. with 32 sacks. Leave at least 100 ft. in casing 2500 CICR Depth
Perforate and squeeze at 856 ft. with 32 sacks. Leave at least 100 ft. in casing 806 CICR Depth
Perforate and squeeze at 0 ft. with 0 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 14 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Richard Murray

Title: OWP Specialist Date: 11/28/2022 Email: g.richard.murray@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: _____

COA Type

Description

0 COA	
-------	--

Attachment List

Att Doc Num

Name

403241368

WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Stamp Upon
Approval

Total: 0 comment(s)