

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403184315

Date Received:

10/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10417

Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Harkins, Liz

719-429-4513

Lharkins@austineexploration.com

Hart, Tim

303-999-5420

thart@fremontpetroleum.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695106762

Inspection Date: 09/21/2022

FIR Submit Date: 09/21/2022

FIR Status: _____

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC

Company Number: 10417

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 417859

Location Name: Woolly Bugger Number: 34-20 County: FREMONT

Qtrqtr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.376641 Longitude: -105.132744

FACILITY - API Number: 05-043-00 Facility ID: 417858

Facility Name: Woolly Bugger Number: 34-20

Qtrqtr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.376641 Longitude: -105.132744

CORRECTIVE ACTIONS:

1 ☒ CA# 164810

Corrective Action: REMOVE WEEDS PER RULE 606.

Date: 10/03/2022

Response: CA COMPLETED

Date of Completion: 09/27/2022

Operator Comment: COGCC Field Inspector, Tom Beardslee, arrived on location that serves 4 wells on 9/21/22. Crews had been performing weed maintenance during inspection date of 9/21/22 and weed removal was completed work on 9/22/22. Upon receiving FIR via email on 9/27/22, Operator dispatched pumper to take photos of work completed in area. See photo Attachment.

COGCC Decision: Approved via an AMI

COGCC
Representative:

2 ☒ CA# 164811

Corrective Action: clean up per Rule 1002.f2(c).

Date: 10/03/2022

Response: CA COMPLETED

Date of Completion: 09/29/2022

Operator
Comment: FIR notification received via email on 9/27/22 indicated area of stained soil around wellhead. Operator dispatched crew on 9/29/22 who cleaned and removed impacted soil and replaced with clean soil. See photo Attachment.

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This FIRR is in response to the Woolly Bugger 34-20, location ID #417859 , field inspection for the Woolly Bugger 34-20 facility, ID# 417858 and targets specifically, the Woolly Bugger 34-20, API#05-043-06194.
-Corrective actions for weed removal were completed. Crews had been performing weed maintenance during inspection date of 9/21/22 and completed work on 9/22/22. Upon receiving FIR via email on 9/27/22, Operator dispatched pumper to take photos of work completed in area. See photo Attachment. Maintenance (mowing, trimming, spraying and cutting) has been on-going all summer to keep up with growth spurred by monsoon rains.
-Corrective actions for impacted stained soil around the wellhead was completed on 9/29/22. See photo Attachment.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liz Harkins

Signed: _____

Title: Entineer

Date: 10/3/2022 11:50:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403184315	FIR RESOLUTION SUBMITTED
403184493	Post CA photos

Total Attach: 2 Files