

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403184317

Date Received:  
10/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10417  
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Harkins, Liz</u>	<u>719-429-4513</u>	<u>Lharkins@austinexploration.com</u>
<u>Hart, Tim</u>	<u>303-999-5420</u>	<u>thart@fremontpetroleum.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695106772  
Inspection Date: 09/21/2022 FIR Submit Date: 09/21/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC Company Number: 10417  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 425146

Location Name: Paiute Number: 34-29 County: FREMONT  
Qtrqtr: SWSE Sec: 29 Twp: 19S Range: 69W Meridian: 6  
Latitude: 38.361498 Longitude: -105.133770

FACILITY - API Number: 05-043-00 Facility ID: 425132

Facility Name: Paiute Number: 34-29  
Qtrqtr: SWSE Sec: 29 Twp: 19S Range: 69W Meridian: 6  
Latitude: 38.361498 Longitude: -105.133770

CORRECTIVE ACTIONS:

1  CA# 164813

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002. (2).D. Date: 10/03/2022

Response: CA COMPLETED Date of Completion: 09/29/2022

Operator Comment: On 9/29/22 Operator conducted maintenance on the chemical pump and cleaned a chemical stand and concrete base. Impacted soils were removed and disposed and replaced with clean soil.

COGCC Decision: Approved pending re-inspection

COGCC Representative: ONSITE REINSPECTION HAS ALLREADY BEEN PERFORMED

**2**  CA# 164814

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D.

Date: 10/03/2022

Response: CA COMPLETED

Date of Completion: 09/29/2022

Operator Comment: On 9/29/22, Operator cleaned wellhead and tightened the stuffing box and performed rod lubricator maintenance. Impacted soil around the well head was removed and replaced with clean soil. See photo Attachment.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Operator received FIR notifications on the Paiute 34-29 lease on 9/27/22 via email. Operator responded with corrective actions on 9/29/22 to conduct equipment maintenance and cleanup impacted soils near a chemical stand and also the wellhead. See photo Attachment.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liz Harkins

Signed: \_\_\_\_\_

Title: Engineer

Date: 10/3/2022 11:51:37 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403184317	FIR RESOLUTION SUBMITTED
403184491	Post CA Photos

Total Attach: 2 Files