

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403212393

Date Received:
10/28/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10670
Name of Operator: MALLARD EXPLORATION LLC
Address: 1400 16TH STREET SUITE 300
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Erin Mathews</u>	<u>720-543-7959</u>	<u>emathews@mallardexploration.com</u>
<u>DYK, DUSTIN</u>	<u>720-543-7954</u>	<u>ddyk@mallardexploration.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105530
Inspection Date: 10/11/2022 FIR Submit Date: 10/20/2022 FIR Status: _____

Inspected Operator Information:

Company Name: MALLARD EXPLORATION LLC Company Number: 10670
Address: 1400 16TH STREET SUITE 300
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455657

Location Name: Bashor 9-60 Number: 27B Pad County: _____
Qtrqtr: NWNE Sec: 27 Twp: 9N Range: 60W Meridian: 6
Latitude: 40.727099 Longitude: -104.074229

FACILITY - API Number: 05-123-00 Facility ID: 455657

Facility Name: Bashor 9-60 Number: 27B Pad
Qtrqtr: NWNE Sec: 27 Twp: 9N Range: 60W Meridian: 6
Latitude: 40.727099 Longitude: -104.074229

CORRECTIVE ACTIONS:

1 CA# 165571

Corrective Action: Comply with Rule 606. Date: 10/11/2022
Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED Date of Completion: 10/13/2022

Operator Comment: Interim reclamation to pull the pad back began on 10/13/2022. Weedy vegetation was removed during dirt work activities and seeding and straw mulching has been completed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 CA# 165572

Corrective Action: Comply with Rule 606.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/13/2022

Operator Comment: Interim reclamation to pull the pad back began on 10/13/2022. Trash was picked up and disposed of as part of interim reclamation activities.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

3 CA# 165573

Corrective Action: Comply with Rule 606.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/13/2022

Operator Comment: Interim reclamation to pull the pad back began on 10/13/2022. Unused equipment was removed from location as part of interim reclamation activities.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

4 CA# 165574

Corrective Action: Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/27/2022

Operator Comment: Interim reclamation to pull the pad back began on 10/13/2022. Seeding and straw mulching was completed by 10/27/2022.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

5 CA# 165575

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/13/2022

Interim reclamation to pull the pad back began on 10/13/2022. Areas of rill erosion were repaired as part of pad

Operator Comment: pull back operations.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Interim Reclamation operations were commenced on 10/13/2022 and finished on 10/27/2022.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Erin Mathews

Signed: _____

Title: VP Development

Date: 10/28/2022 5:50:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403212393	FIR RESOLUTION SUBMITTED
403212401	Photos

Total Attach: 2 Files