

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403254886

Date Received:
12/08/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 4 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kellerby, Shaun</u>		<u>shaun.kellerby@state.co.us</u>
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>
<u>Ramsey, Scott</u>		<u>scott.ramsey@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800968
Inspection Date: 11/23/2022 FIR Submit Date: 12/05/2022 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 311677

Location Name: HARRIS-67S94W Number: 5SWNE County: _____
Qtrqtr: SWNE Sec: 5 Twp: 7S Range: 94W Meridian: 6
Latitude: 39.468371 Longitude: -107.910263

FACILITY - API Number: 05-045-00 Facility ID: 311677

Facility Name: HARRIS-67S94W Number: 5SWNE
Qtrqtr: SWNE Sec: 5 Twp: 7S Range: 94W Meridian: 6
Latitude: 39.468371 Longitude: -107.910263

CORRECTIVE ACTIONS:

2 CA# 166403

Corrective Action: Install proper guy line markers per Rule 1003.a or remove anchors if unnecessary equipment. Date: 12/14/2022

Response: CA COMPLETED Date of Completion: 12/07/2022

Operator Comment: TEP production personnel located and marked four guy line anchors on 12/07/22. The Field Inspection Report states that 6 anchors required marking, but the inspection photos only show 3 anchors. If additional anchors are found, TEP will mark those as well. TEP has marked all anchors that could be located. This corrective action is

complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

Upon reinspection Inspector will locate and identify remaining unmarked anchors if observed.

OPERATOR COMMENT AND SUBMITTAL

Comment: TEP production personnel located and marked four guy line anchors on 12/07/22. The Field Inspection Report states that 6 anchors required marking, but the inspection photos only show 3 anchors. If additional anchors are found, TEP will mark those as well. TEP has marked all anchors that could be located. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 12/8/2022 3:01:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403254886	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files