

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tank requires a new NFPA placard, produced water tank lacks all placards, see attached photos.		
Corrective Action:	Install signs to comply with Rule 605.h.	Date:	02/10/2023

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	Calibration card is current		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:	Unknown capacity				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST				
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 481184 Type: TANK API Number: - Status: AC Insp. Status: SI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date:
Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 12/7/2022 at approximately 12:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KPK Kammerzell 2-16 Tank Battery location #481184 in Weld County, Colorado. While there, I observed that the crude oil tank required a new NFPA placard and the produced water tank lacked all required placards. During this inspection the following possible compliance issues were observed: Rule 605.h. with a corrective action date of 2/10/2023. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	12/07/2022

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403253487	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5937178
697006843	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5937160