

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2022

Submitted Date:

12/14/2022

Document Number:

697601984**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Ahmadian, Alexander 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Meis, Craig		cmeis@kpk.com	<a href="#">KPK Environmental</a>
Graber, Nikki		nikki.graber@state.co.us	
-, Marcom		primarycontractor@marcomllc.net	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480994	SPILL OR RELEASE	CL	04/01/2022		-	UPRR 43 PAN AM I5	EI

**General Comment:**

This is an environmental inspection for Spill ID 480994 UPRR 43 PAN AM I5. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Signage is adequate at the wellhead.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds are overgrown within the excavation.		
Corrective Action:	Comply with Rule 606		Date: 12/21/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Fencing around the excavation is inadequate.		
Corrective Action:	The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.		Date: 12/21/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 480994 Type: SPILL OR API Number: - Status: CL Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601985	Photo Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5944199">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5944199</a>