

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403253650

Date Received:
12/15/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96340

Name of Operator: WIEPKING-FULLERTON ENERGY LLC

Address: 106 GLENMOOR LN

City: ENGLEWOOD State: CO Zip: 80113

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name

Phone

Email

Shalberg, Greg

(719) 688-3547

gregshalberg@aol.com

Boone, Linda

(720) 271-8605

LDBoonePar@aol.com

Halde, Kerry

(719) 340-0329

haldeoil@hotmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688313214

Inspection Date: 09/29/2022

FIR Submit Date: 11/13/2022

FIR Status:

Inspected Operator Information:

Company Name: WIEPKING-FULLERTON ENERGY LLC

Company Number: 96340

Address: 106 GLENMOOR LN

City: ENGLEWOOD State: CO Zip: 80113

LOCATION - Location ID: 309645

Location Name: FORRISTAL RANCH STATE-610S55W Number: 30NENW County: LINCOLN

Qtrqtr: NENW Sec: 30 Twp: 10S Range: 55W Meridian: 6

Latitude: 39.155090 Longitude: -103.596310

FACILITY - API Number: 05-073-00 Facility ID: 297880

Facility Name: FORRISTAL RANCH STATE Number: 21-30 #5

Qtrqtr: NENW Sec: 30 Twp: 10S Range: 55W Meridian: 6

Latitude: 39.155090 Longitude: -103.596310

CORRECTIVE ACTIONS:

1 CA# 166195

Corrective Action: Install sign to comply with Rule 605.h.

Date: 12/15/2022

Response: CA COMPLETED

Date of Completion: 12/15/2022

New decals have been ordered and are in transit.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 166196

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/15/2022

Response: CA COMPLETED

Date of Completion: 12/15/2022

Operator
Comment:

During prior routine activities, the operator rebuilt the west wall of the berm using a lighter colored dirt than the red rock that had previously been used to cap the berm. The area noted by the inspector has been smoothed out. The site has been added to the list of spots for touch up seeding to be conducted during the winter.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Wiepking

Signed:

Title: Managing Member

Date: 12/15/2022 2:03:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|--|--|
| | |
|--|--|

Total Attach: 0 Files