

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

RECEIVED

SEP 26 1994

COLO. OIL & GAS CONS. COMM.

FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input type="checkbox"/> OTHER		5. FEDERAL/INDIAN OR STATE LEASE NO.
2. NAME OF OPERATOR Walsh Production, Inc.		6. PERMIT NO.
3. ADDRESS OF OPERATOR P. O. Box 30		7. API NO. <u>5040</u> 001 05-0400
CITY Sterling	STATE CO	8. WELL NAME Noonen UPRR
ZIP CODE 80751		9. WELL NUMBER #1-B
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL, 1845' FWL ✓ At proposed prod. zone		10. FIELD OR WILDCAT Noonen Ranch
12. COUNTY Adams		11. QTR. QTR. SEC., T.R. AND MERIDIAN SE SW Sec. 13-T3S-R59W ✓

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
☐ MULTIPLE COMPLETION
☐ COMMINGLE ZONES
☐ FRACTURE TREAT
☐ REPAIR WELL
☐ OTHER _____

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT
(SUBMIT 3RD PARTY CEMENT VERIFICATION
AND JOB LOG)
☐ ABANDONED LOCATION (WELL NEVER DRILLED -
SITE MUST BE RESTORED WITHIN 6 MONTHS)
☐ REPAIRED WELL
☐ OTHER

*Use Form 5 - Well Completion or Recompletion Report and Log
for subsequent report of Multiple/Commingle Completions
and Recompletions

13C. NOTIFICATION OF:

- ☐ SHUT-IN/TEMPORARILY ABANDONED
(DATE _____)
(REQUIRED EVERY 6 MONTHS)
☐ PRODUCTION RESUMED
(DATE _____)
☐ LOCATION CHANGE (SUBMIT NEW PLAT)
☐ WELL NAME CHANGE
☐ OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones.pertinent

15. DATE OF WORK November 1, 1994 thru November 30, 1994

1. Dump sand to cover perfs @ 6020'-6075'.
2. Set 5 sack cement plug on top of sand.
3. Shoot and recover casing at approximately 4500'.
4. Set 30 sack cement plug in and out of base of surface pipe.
5. Set 5 sack cement plug at surface.
6. Cut off surface casing 4' below ground level and weld on cap.
7. Restore surface disturbance.

16. I hereby certify that the foregoing is true and correct

SIGNED

David G. WalshTELEPHONE NO. 303-522-1839

NAME (PRINT)

David G. Walsh

TITLE

Operator

DATE

9-23-94

(This space for Federal or State office use)

SR. PETROLEUM ENGINEER

O & G Cons. Comm.

DATE

OCT 12 1994

APPROVED

D. K. [Signature]

CONDITIONS OF APPROVAL, IF ANY:

Also set 30 sk plug at 5 1/2" casing stub.