



99999999

OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 001 - 5044		LEASE NAME: UPRR - Norner 2B	
LOCATION: NESW 13-35-59W		OPERATOR: Walsh	
DATE: 5-28-97		INSPECTOR: EBB	
Insp. Type: ID	Insp. Status: SI	PA: Y N	Pass/Fail: P (F) Viol.: (Y) N NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	needs update	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	pits eroded + washed out	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	2-300, VHT	
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)	no motor on pump	
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	grassland	
<b>Miscellaneous</b>		

RECEIVED  
JUL 10 97  
COGCC

<b>CORRECTIVE ACTION REQUIRED:</b> Comply with Rule 326 b. Well shut in since 1990.	
<b>Date Corrective Action Required By:</b> 6-30-97	<b>Date Remedied:</b>

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

