

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2022

Submitted Date:

12/16/2022

Document Number:

694100039**FIELD INSPECTION FORM**Loc ID 331031 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 760 HORIZON DRIVE STE 401City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		nbl_djbu_inspections@nblen rgy.com	<a href="#">ALL INSPECTIONS ONLY</a>
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**General Comment:**

This is an environmental inspection for Location ID: 331031 Noble Beeler 22-11. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: No spill present.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 331031 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** Wattles surrounding downslope of pad are in good condition. Continue to monitor as there is a large amount of soil material upslope with potential to erode after a large rain event. Silt fence may be needed to contain in the future and prevent runoff. Evidence of slight erosion is present in the form of rills.**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Comment	Soil stockpile present with no erosion control.			
Corrective Action	For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e. Install or repair required BMPs per Rule 1002.f.(2)C			Date: 12/23/2022

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100041	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950998">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950998</a>