

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403263782

Date Received:
12/16/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702801044

Inspection Date: 12/09/2022

FIR Submit Date: 12/13/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 421020

Location Name: Shaeffer Number: 24-5H (J12W) County: _____

Qtrqtr: NWSE Sec: 12 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.458790 Longitude: -107.721820

FACILITY - API Number: 05-045-00 Facility ID: 421020

Facility Name: Shaeffer Number: 24-5H (J12W)

Qtrqtr: NWSE Sec: 12 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.458790 Longitude: -107.721820

CORRECTIVE ACTIONS:

1 ☒ CA# 166554

Corrective Action: Eliminate possibility of wildlife to enter open lines.

Date: 12/23/2022

Response: CA COMPLETED

Date of Completion: 12/15/2022

Operator Comment: Capped and sealed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2  CA# 166555

Corrective Action: Remove unused risers.

Date: 01/12/2023

Response: CA COMPLETED

Date of Completion: 12/15/2022

Operator Comment: We cannot remove the risers, as they are all tied to the main sales line. However, darts, seals, and tags were installed. See photo.

COGCC Decision: **Not Approved**

COGCC Representative: Operator has attached a photo of tagged out risers which appear to be located at the southeast of the upper production pad. After discussion of the Operator comment in this FIRR with Staff, it was determined that the four (4) risers at the southeast of the upper production pad do not need to be removed.

This FIRR Corrective Action Item is "Not Approved" due to the presence of the two (2) risers at the separators at the northeast of the lower production pad. These two risers appear to be associated with the two plugged and abandoned wells on location. The wells have been plugged and abandoned, separators have been removed. Therefore, the associated riser equipment must also be removed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 12/16/2022 12:10:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403263782	FIR RESOLUTION SUBMITTED
403263784	Risers Addressed

Total Attach: 2 Files